

Part 573 Safety Recall Report

16V-496

Manufacturer Name : Wilson Trailer Company

Submission Date : JUN 28, 2016

NHTSA Recall No. : 16V-496

Manufacturer Recall No. : 132P



Manufacturer Information :

Manufacturer Name : Wilson Trailer Company

Address : 4400 S. Lewis Boulevard
P.O. Box 6300 Sioux City IA
51106-6300

Company phone : 712-252-6551

Population :

Number of potentially involved : 10

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2015-2015 Wilson DWH-550 AND CD-1080

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : HOPPER BOTTOM SEMI GRAIN COMMODITY TRAILER AND PLATFORM SEMI TRAILER

Production Dates : NOV 20, 2015 - NOV 20, 2015

VIN Range 1 : Begin : 1W14482A4G2267964 **End :** 1W14482AXG2267967 Not sequential

VIN Range 2 : Begin : 4WW5532A3G6624069 **End :** 4WW5532AXG6625185 Not sequential

Description of Defect :

Description of the Defect : UNDER A UNIQUE SET OF CIRCUMSTANCES, IT IS POSSIBLE (THOUGH NOT PROBABLE) FOR AN INTERNAL LEAK TO DEVELOP IN THE BENDIX SR-5 SPRING BRAKE VALVE. THIS VALVE WAS MANUFACTURED BY BENDIX BETWEEN 1/1/2015 AND 3/4/2016.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : IF AN INTERNAL LEAK DEVELOPS THE RESULT WILL BE SLOW APPLICATION OF THE SPRING BRAKES WHEN PARKING THE TRAILER.. IF UNCOUPLED FROM THE TRACTOR AND THE LEAKAGE DEVELOPS, LOSS OF AIR PRESSURE IN THE TRAILER RESEVOIR WILL RESULT.

Description of the Cause : DIAMETER OF INTERNAL PORT FOR CHECK VALVE WAS INCORRECTLY MILLED.

Identification of Any Warning that can Occur : THE LEAK WILL BE HEARD OR OBSERVED AT THE SUPPLY (RED)GLADHAND WHEN UNCOUPLED FROM THE TRACTOR. IF COUPLED TO A TRACTOR, A LEAK MAY BE HEARD FROM THE EXHAUST OF THE PARK CONTROL VALVE

OR FROM THE TRACTOR PROTECTION VALVE.

Supplier Identification :

Component Manufacturer

Name : BENDIX COMMERCIAL VEHICLE SYSTEMS LLC
Address : 901 CLEVELAND STREET
ELYRIA OHIO 44035
Country : United States

Chronology :

WILSON TRAILER COMPANY WAS NOTIFIED BY MAIL OF THE START OF A VOLUNTARY SAFETY RECALL CAMPAIGN BY BENDIX COMMERCIAL VEHICLE SYSTEMS INVOLVING THEIR SR-5 SPRING BRAKE VALVE. THEY NOTIFIED WILSON TRAILER COMPANY THAT WILSON HAD PURCHASED 11 OF THESE VALVES. BENDIX ASSIGNED RECALL NUMBER IS 16E045. WILSON TRAILER IDENTIFIED THE 10 TRAILERS PRODUCED WITH THIS VALVE. THE REMAING VALVE IS IN INVENTORY AND HAS BEEN QUARANTINED.

Description of Remedy :

Description of Remedy Program : WILSON TRAILER HAS BEEN TOLD THAT BENDIX HAS NOT FINALIZED A REMEDY AS OF THIS TIME. ONCE A REMEDY IS IDENTIFIED BY BENDIX, WILSON TRAILER COMPANY WILL NOTIFY DEALERS AND CUSTOMERS OF THE RECALL AND PROVIDE THE REMEDY FREE OF CHARGE TO THE CUSTOMER.

How Remedy Component Differs from Recalled Component : A BLACK OR GREEN TIE WRAP WILL BE AFIXED TO THE REPAIRED SR-5 VALVE.

Identify How/When Recall Condition was Corrected in Production : UNKNOWN AT THIS TIME

Recall Schedule :

Description of Recall Schedule : RECALL SCHEDULE WILL BE IDENTIFIED ONCE REMEDY IS AVAILABLE FROM BENDIX

Planned Dealer Notification Date : AUG 12, 2016 - AUG 12, 2016

Planned Owner Notification Date : AUG 19, 2016 - AUG 19, 2016

* NR - Not Reported