

Part 573 Safety Recall Report

16V-570

Manufacturer Name : e-ride Industries**Submission Date :** OCT 24, 2016**NHTSA Recall No. :** 16V-570**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : e-ride Industries

Address : 3032 92nd Ave

Princeton MN 55371

Company phone : 389-9139

Population :

Number of potentially involved : 1,038

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2005-2016 e-ride Industries EXV2

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : NR

Descriptive Information : 2 passenger electric utility vehicle

Production Dates : MAR 01, 2005 - JUL 29, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2005-2016 e-ride Industries EXV4

Vehicle Type : LOW VOLUME VEHICLES

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : 4 passenger low speed electric utility/passenger vehicle

Production Dates : MAR 03, 2005 - JUL 19, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Location of side red reflectors needs to move to rear of vehicle and vehicle is missing a red reflector on the back of the vehicle.

FMVSS 1 : 500 - Low speed vehicles

FMVSS 2 : NR

Description of the Safety Risk : Does meet compliance. Rear end of the vehicle not as visible as it could be with an additional reflector.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

A 3rd party tested our vehicle for article 500 compliance and pointed out the reflectors needed to be moved back an there needed to be a reflector added to the back of the vehicle. e-ride Ind. was notified on 7/13/16.

Description of Remedy :

Description of Remedy Program : A red reflector will be added to both sides of the rear bumper that will wrap around the bumper so it is visible from the side of the vehicle and the rear of the vehicle.

How Remedy Component Differs from Recalled Component : Reflectors were on the side of the vehicle, now will be on the side and back of the rear bumper.

Identify How/When Recall Condition was Corrected in Production : Immediately. First vehicles will be shipped on 7/29/16 with the remedy

Recall Schedule :

Description of Recall Schedule : NR
Planned Dealer Notification Date : AUG 01, 2016 - SEP 01, 2016
Planned Owner Notification Date : AUG 01, 2016 - NOV 30, 2016

* NR - Not Reported