

Part 573 Safety Recall Report

16V-703

Manufacturer Name : Halcore Group, Inc.

Submission Date : OCT 03, 2016

NHTSA Recall No. : 16V-703

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Halcore Group, Inc.

Address : 3800 McDowell Road
Grove City OH 43123

Company phone : 999

Population :

Number of potentially involved : 41

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2017 American Emergency Vehicle Traumahawk Ambulance

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : The primary product effected by this 573 are emergency vehicles ambulances. AEV has been notified by E.V.S. Ltd. that a defect which relates to motor vehicle safety exists in certain E.V.S. Ltd. seats manufactured with seat tracks provided by Dometic Corporation from March 22,2016 through August 29 2016.

Production Dates : AUG 01, 2016 - SEP 28, 2016

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Independent testing initiated by E.V.S. Ltd. has revealed that certain seat tracks furnished by Dometic Corporation during the afore mentioned date range, may be impaired by a defect which allows the seat track to release unexpectedly in the event of rapid deceleration.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of an accident, such release could allow the seat to move forward at a high rate of speed. This may increase severity of injury or death. The defect does not increase the likelihood of a crash in any way.

Description of the Cause : EVS Ltd. has not mentioned the cause of the defect.

Identification of Any Warning that can Occur : EVS Ltd. has not mentioned any warning signs associated with this defect.

Supplier Identification :

Component Manufacturer

Name : EVS Ltd

Address : PO BOX 1863

3702 WEST SAMPLE STREET SOUTH BEND INDIANA 46624

Country : United States

Chronology :

AEV received the notice of the recall from EVS LTD on 9/22/2016.

Description of Remedy :

Description of Remedy Program : EVS LTD will provide replacement gold tracks for the units that are affected. Their goal is to ship the replacement track out to AEV and drop ship to any end user that may need the part. AEV will notify both dealers and customers that are affected of the recall and provide them with the EVS Ltd instructions to remedy this defect.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Late September AEV as the lessor was notified by our seat Vendor EVS Ltd that Dometic the slide manufacturer had an issue. Inventory was inspected, balance on hand was quarantined until replacement parts received. Vehicles already delivered will receive recall notice, 1 seat sold as a part sale end user contacted. 48 seats received with multiple seats for some trucks affecting 41 production vehicles.

Recall Schedule :

Description of Recall Schedule : Planned Dates are tentative. AEV will notify Independent Dealer Network and customers upon receipt of a Recall Identification Code number.

Planned Dealer Notification Date : OCT 31, 2016 - NOV 30, 2016

Planned Owner Notification Date : OCT 31, 2016 - NOV 30, 2016

* NR - Not Reported