

# Part 573 Safety Recall Report

# 16V-714

**Manufacturer Name :** Mack Trucks, Inc.

**Submission Date :** OCT 04, 2016

**NHTSA Recall No. :** 16V-714

**Manufacturer Recall No. :** SC0405



## Manufacturer Information :

**Manufacturer Name :** Mack Trucks, Inc.

**Address :** 2100 Mack Boulevard

PO Box M Allentown PA 18105-5000

**Company phone :** 610-709-2131

## Population :

**Number of potentially involved :** 57

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2017-2017 Mack Pinnacle, CHU and CXU

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :** OTHER

**Power Train :** DIESEL

**Descriptive Information :** Certain 2017 Pinnacle model trucks manufactured from March 9, 2016 through May 19, 2016 with a Goodyear G399A LHS 295/75R22.5 LRG tire

**Production Dates :** MAR 09, 2016 - MAY 19, 2016

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** A cure anomaly resulting in incomplete adhesion which could lead to partial tread separation.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** As a result of the cure anomaly, a partial tread separation could lead to vehicle damage or a motor vehicle crash.

**Description of the Cause :** An irregular cure condition existed due to a curing press set-up error that was restricted to two curing presses during the specified time period included in Goodyear's defect report.

**Identification of Any Warning that can Occur :** Noise or vibration may occur prior to a partial tread separation.

**Supplier Identification :****Component Manufacturer**

Name : Goodyear Tire & Rubber Company  
Address : 200 Innovation Way  
Akron OHIO 44316  
Country : United States

**Chronology :**

September 27, 2016 Goodyear notifies Mack Trucks that certain tires provided to Mack Trucks contain a safety-related defect

October 4, 2016 Mack Trucks submits a defect report to document the number of trucks affected by the Goodyear recall

**Description of Remedy :**

Description of Remedy Program : The tires will be inspected for the suspect lot codes and replaced as required. Pre-notification reimbursement requests will be addressed according to the established reimbursement plan that is on file with NHTSA.

How Remedy Component Differs from Recalled Component : Reference Goodyear's defect report 16T-013

Identify How/When Recall Condition was Corrected in Production : Reference Goodyear's defect report 16T-013

**Recall Schedule :**

Description of Recall Schedule : Dealer notifications will occur by October 10, 2016. Owner notification letters will be mailed no later than October 31, 2016

Planned Dealer Notification Date : OCT 10, 2016 - OCT 10, 2016

Planned Owner Notification Date : OCT 31, 2016 - OCT 31, 2016

\* NR - Not Reported