

Part 573 Safety Recall Report

16V-714

Manufacturer Name : Mack Trucks, Inc.

Submission Date : JAN 17, 2017

NHTSA Recall No. : 16V-714

Manufacturer Recall No. : SC0405



Manufacturer Information :

Manufacturer Name : Mack Trucks, Inc.

Address : 2100 Mack Boulevard

PO Box M Allentown PA 18105-5000

Company phone : 610-709-2131

Population :

Number of potentially involved : 57

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Mack Pinnacle, CHU and CXU

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Certain 2017 Pinnacle model trucks manufactured from March 9, 2016 through May 19, 2016 with a Goodyear G399A LHS 295/75R22.5 LRG tire

Production Dates : MAR 09, 2016 - MAY 19, 2016

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : A cure anomaly resulting in incomplete adhesion which could lead to partial tread separation.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : As a result of the cure anomaly, a partial tread separation could lead to vehicle damage or a motor vehicle crash.

Description of the Cause : An irregular cure condition existed due to a curing press set-up error that was restricted to two curing presses during the specified time period included in Goodyear's defect report.

Identification of Any Warning that can Occur : Noise or vibration may occur prior to a partial tread separation.

Supplier Identification :**Component Manufacturer**

Name : Goodyear Tire & Rubber Company
Address : 200 Innovation Way
Akron OHIO 44316
Country : United States

Chronology :

September 27, 2016 Goodyear notifies Mack Trucks that certain tires provided to Mack Trucks contain a safety-related defect

October 4, 2016 Mack Trucks submits a defect report to document the number of trucks affected by the Goodyear recall

Description of Remedy :

Description of Remedy Program : The tires will be inspected for the suspect lot codes and replaced as required. Pre-notification reimbursement requests will be addressed according to the established reimbursement plan that is on file with NHTSA.

How Remedy Component Differs from Recalled Component : Reference Goodyear's defect report 16T-013

Identify How/When Recall Condition was Corrected in Production : Reference Goodyear's defect report 16T-013

Recall Schedule :

Description of Recall Schedule : Dealer notifications will occur by October 10, 2016. Owner notification letters will be mailed no later than October 31, 2016. Goodyear tires will conduct the recall and will report quarterly completion rates to NHTSA beginning with Q4-2017.

Planned Dealer Notification Date : OCT 10, 2016 - OCT 10, 2016

Planned Owner Notification Date : OCT 31, 2016 - OCT 31, 2016

* NR - Not Reported