

# Part 573 Safety Recall Report

# 16V-734

**Manufacturer Name :** Chrysler (FCA US LLC)

**Submission Date :** OCT 11, 2016

**NHTSA Recall No. :** 16V-734

**Manufacturer Recall No. :** S76



## Manufacturer Information :

**Manufacturer Name :** Chrysler (FCA US LLC)

**Address :** 800 Chrysler Drive  
CIMS 482-00-91 Auburn Hills MI  
48326-2757

**Company phone :** 1-800-853-1403

## Population :

**Number of potentially involved :** 182,308

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2016-2017 Jeep Wrangler

**Vehicle Type :**

**Body Style :** SUV

**Power Train :** NR

**Descriptive Information :** All 2016 and 2017 MY Jeep Wrangler ("JK") vehicles built before August 14, 2016.

**Production Dates :** JUN 16, 2015 - AUG 14, 2016

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Defect :

**Description of the Defect :** Under certain crash conditions, rotation of the headlamp can cause the sensor wiring to pull and detach from the front impact sensor before a signal is recorded by the Occupant Restraint Controller ("ORC").

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** This defect may result in non-deployment of airbag and pretensioner in certain crash events where deployment is expected, which may increase the risk of injury.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

Please see the attached supplemental information titled "FCA US LLC Chronology - Impact Sensor Wire Routing - 10112016.pdf".

**Description of Remedy :**

Description of Remedy Program : FCA US will conduct a Voluntary Safety Recall on all affected vehicles with a remedy to be determined at a later date.  
FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : FCA US will notify dealers and begin notifying owners on or about November 25, 2016.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported