

**Part 573 Safety Recall Report****16V-761****Manufacturer Name :** Entegra Coach**Submission Date :** OCT 18, 2016**NHTSA Recall No. :** 16V-761**Manufacturer Recall No. :** 9903329**Manufacturer Information :**

Manufacturer Name : Entegra Coach

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 1-800-945-4787

**Population :**

Number of potentially involved : 671

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2016-2017 Class A Motor home Cornerstone and Anthem

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : 2016 Anthem G14A8051-8058 G14B8051-8189 G14D8052-8074 G14H8051-8075  
 G14G8054-8062 G14N8051-8109  
 2017 Anthem H14A8051-8064 H14B8051-8141 H14D8051-8060 H14H8051-8069  
 H14N8051-8076  
 2016 Cornerstone G16A8052-8076 G16B8051-8141 G16J8051-8056  
 G16K8051-8080  
 2017 Cornerstone H16A8051-8059 H16B8051-8107 H16J8051-8053  
 H16K8051-8066 H16W8052-8059

Production Dates : APR 07, 2015 - AUG 18, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Tempurpedic Sealy Mattress installed by Jayco - Entegra Division during production process is not 302 compliant -

FMVSS 1 : 302 - Flammability of interior materials

FMVSS 2 : NR

Description of the Safety Risk : The rate of burn is quicker than allowed under code 302 and may not allow vehicle occupant required time to exit which may lead to personal injury / death .

Description of the Cause : The Tempurpedic mattress was spec'd into build of motorhomes without the knowledge that the mattress was NOT compliant to FMVSS code 302

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Fabric Technologies Inc  
Address : 516 Pine Creek Court  
Elkhart INDIANA 46516  
Country : United States

**Chronology :**

The 16 CFR part 1633 compliance testing determined the Tempurpedic mattress to be compliant - since 1633 is more stringent testing than the 302 testing - conclusion was made that it would be compliant to FMVSS code 302. Additional outsourced testing of the Tempurpedic mattress ( requested by Jayco - Entegra Division) determined the mattress is NOT compliant to code 302. Immediate stop was made on production line and mattress orders cancelled for future builds that call out the Tempurpedic Sealy mattress -

**Description of Remedy :**

|  |  |
|--|--|
| Description of Remedy Program :                                  | Replace existing King size Sealy Tempurpedic mattress with a King size Sleep Number Mattress at no charge  |
| How Remedy Component Differs from Recalled Component :           | Brand of mattress  |
| Identify How/When Recall Condition was Corrected in Production : | Production immediately stopped install of the Tempurpedic and replaced with Sleep Number mattress and replaced in all motorhomes still on site in various stages of production. ECN was filed for all future builds. |

**Recall Schedule :**

|                                    |                             |
|------------------------------------|-----------------------------|
| Description of Recall Schedule :   | NR                          |
| Planned Dealer Notification Date : | NOV 18, 2016 - NOV 18, 2016 |
| Planned Owner Notification Date :  | NOV 18, 2016 - NOV 18, 2016 |

\* NR - Not Reported