

# Part 573 Safety Recall Report

# 16V-824

**Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** NOV 08, 2016**NHTSA Recall No. :** 16V-824**Manufacturer Recall No. :** FL-728**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

**Population :**

Number of potentially involved : 863

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2017-2017 Freightliner Cascadia

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain 2017 vehicles manufactured from January 24, 2016 to October 10, 2016 with Goodyear G399A LHS 295/75R22.5 LRG tires.

Production Dates : JAN 24, 2016 - OCT 10, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 2 : 2017-2017 Freightliner Business Class M2

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain 2017 vehicles manufactured from January 24, 2016 to October 10, 2016 with Goodyear G399A LHS 295/75R22.5 LRG tires.

Production Dates : JAN 24, 2016 - OCT 10, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

Vehicle 3 : 2017-2017 Freightliner 122SD

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain 2017 vehicles manufactured from January 24, 2016 to October 10, 2016 with Goodyear G399A LHS 295/75R22.5 LRG tires.

Production Dates : JAN 24, 2016 - OCT 10, 2016

VIN Range 1 : Begin : NR End : NR

 Not sequential

**Description of Defect :**

Description of the Defect : Goodyear recall 16T-013 states "A cure anomaly resulting in incomplete adhesion which could lead to partial tread separation."

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Goodyear recall 16T-013 states "A partial tread separation could lead to vehicle damage or a motor vehicle crash."

Description of the Cause : NR

Identification of Any Warning  
that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Goodyear Tire & Rubber Company

Address : 200 Innovation Way

Akron OHIO 44316

Country : United States

**Chronology :**

In late September 2016, DTNA is made aware of Goodyear Tire Recall and opens an investigation. October 2016, DTNA decided to initiate a voluntary safety recall.

**Description of Remedy :**

Description of Remedy Program : DTNA will inspect and replace affected tires where required. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a supplemental report when available.

How Remedy Component Differs  
from Recalled Component : NR

Identify How/When Recall Condition  
was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : DTNA will notify affected customers. Customer notification will be made by first class mail using Daimler Trucks North America records to determine the customer affected.

Planned Dealer Notification Date : JAN 06, 2017 - JAN 06, 2017

Planned Owner Notification Date : JAN 06, 2017 - JAN 06, 2017

\* NR - Not Reported