

Part 573 Safety Recall Report

16V-941

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** DEC 22, 2016**NHTSA Recall No. :** 16V-941**Manufacturer Recall No. :** P094**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 550

Address : 555 MACARTHUR BOULEVARD

Estimated percentage with defect : 100 %

MAHWAH NJ 07430

Company phone : 201-760-8534

Vehicle Information :

Vehicle 1 : 2016-2016 Land Rover Range Rover

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016 MY Land Rover Range Rover Vehicles in select VIN range

Production Dates : SEP 01, 2016 - OCT 12, 2016

VIN Range 1 : Begin : SALGS2PF6GA310620 End : SALGS2PF4GA318022 Not sequential

Vehicle 2 : 2016-2016 Land Rover Range Rover Sport

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2016 MY Land Rover Range Rover Sport Vehicles in select VIN range

Production Dates : SEP 08, 2016 - OCT 06, 2016

VIN Range 1 : Begin : SALWR2PF6GA112966 End : SALWG2PF4GA119436 Not sequentialVIN Range 2 : Begin : SALWR2PF5GA664703 End : SALWG2KF3GA664714 Not sequential

Vehicle 3 : 2017-2017 Land Rover Range Rover Evoque

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

Descriptive Information : 2017 MY Land Rover Range Rover Evoque Vehicles in select VIN range

Production Dates : AUG 31, 2016 - SEP 23, 2016

VIN Range 1 : Begin : SALVP2BG6HH178234 End : SALVP2BG1HH184779 Not sequential**Description of Defect :**

Description of the Defect : On certain 2016 MY Land Rover Range Rover, Land Rover Range Rover Sport and certain 2017 MY Land Rover Range Rover Evoque vehicles, the front passenger airbag may not function properly due to a deviation in generant mix ratio.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash of sufficient severity, the front passenger airbag may not deploy when required. Failure to deploy can lead to increased injuries to the front passenger seat occupant.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NCS Pyrotechnie et Technologies SAS

Address : Rue de la Cartoucherie
BP 90010 Survilliers Fosses FOREIGN STATES

Country : France

Chronology :

See Document "JLR P094 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Land Rover dealer who will replace the front passenger airbag. There will be no charge to owners for this repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before February 20, 2017. Notifications to dealers will occur on or December 28, 2016.

Planned Dealer Notification Date : DEC 28, 2016 - DEC 28, 2016

Planned Owner Notification Date : FEB 20, 2017 - FEB 20, 2017

* NR - Not Reported