

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: Recall Campaign 16V-XXX: Driver-Side Front Air Bag Module
Date: Friday, February 05, 2016 6:29:02 PM

Publish Date: February 05, 2016
From: Technical Service
Expiration Date: February 19, 2016

DCSnet Message
Urgent



Subject: Recall Campaign 16V-XXX: Driver-Side Front Air Bag Module

Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians

Message Text:

BMW AG is conducting a Voluntary Safety Recall involving Driver-Side Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated Takata PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls. There are approximately 840,000 vehicles in the US.

At this time, a repair solution is being developed, we will provide an update as more information becomes available. For additional information, please reference the attached SI B65 04 16, Q&A and Legal Recall notification.

Sincerely, Eugene Aton, Technical Service

Attachments:

-  [B650416 Recall Notice\[81673705\].pdf](#)
-  [B650416 QA\[81673704\].pdf](#)
-  [B650416\[81673703\].pdf](#)  [B650416 Recall Notice\[81673705\].pdf](#)
-  [B650416 QA\[81673704\].pdf](#)
-  [B650416\[81673703\].pdf](#)

Recipients: BMW i, All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel