

[Next Unread Message](#)[View Message](#)

Sent on	02	19	2016	Expires on	03	11	2016
From	Motorcycle Field Service						
Subject	STOP SALE NOTICE: 2014 NSS300/A						

STOP SALE NOTICE: 2014 NSS300 /A - REAR BRAKE LINE JOINT TORQUE

Dear Honda Powersports Dealer:

Honda is launching a SAFETY RECALL on model year 2014 NSS300 and NSS300A scooters to torque the rear brake line joint to specification and, if necessary, fill the rear brake reservoir.

Effective immediately, YOU MUST NOT SELL any NEW or USED 2014 NSS300 or NSS300A scooter until it is repaired according to the forthcoming Service Bulletin.

AFFECTED UNITS

All 2014 NSS300 and NSS300A

To search for applicable recalls on a specific unit, use *Unit Information* on *iN* (effective Tuesday, February 23).

To manage your affected inventory, use *eResponsibility Report* (effective Tuesday, February 23).

SERVICE BULLETIN

Service Bulletin NSS300 #2, which includes the affected units, repair procedure, parts information, as well as warranty claim information, will be published on *iN* by Friday, February 26.

PARTS INFORMATION

The repair procedure for this campaign does not require any parts.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters as early as possible, subject to State registration information.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine through TechLine Connect on *iN* or contact your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.

Bradley Little

Manager, National Field Service

Motorcycle Division

Bulletin No.: 16-0045