

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4556
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 11, 2017

Subject: 28030 - Safety Recall
Driver Airbag Abnormal Deployment
Parts Return Reminder

Models: 2016 Chevrolet Colorado, Malibu
2016 GMC Canyon

To: All General Motors Dealers

General Motors released Safety Recall 28030 on March 07, 2016. The total number of U.S. vehicles involved is approximately 1,583. Of those involved vehicles 95% have already been repaired. The original bulletin instructed dealers to hold the original steering wheel airbag assembly, in the service part packaging, until further instructions were provided. These instructions were provided on April 1, 2016 and were further clarified in bulletin revision 28030B on May 3, 2016. To date only 285 airbag modules have been returned.

Please return all airbag modules as soon as possible using the bulletin instructions. Please see the attached bulletin for details.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS