

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS3986
URGENT - DISTRIBUTE IMMEDIATELY


Date: April 1, 2016

Subject: 31820B - Noncompliance Recall
Side Impact Airbag Weld Stud Fractures
Revised VIN List with Seat Airbag Module Locations

Models: 2016 Chevrolet Malibu

To: All Chevrolet Dealers

This message is to inform dealers of an updated VIN list with seat airbag module locations. The new list includes dealer BAC's along with vehicle stock/sold information. To search for your dealership's BAC, open the attached list and use the search function by pressing the "Control" key and the letter "F" key simultaneously on your keyboard. This will bring up the "Find" feature located at the top right of the PDF file as seen below.



Once a vehicle is identified on the list, follow the line across to determine the appropriate airbag replacement. Airbags that require replacement will be indicated with a YES in the column. **Ensure that you follow the correct line across and review all columns.**

Required repairs for this recall are determined by the VIN of each involved vehicle. Dealers are to confirm which seat airbag modules are affected, this may include any combination of left, right, front, and/or rear seat airbag modules. **To determine the appropriate repair and which parts are required**, refer to the attached VIN list with seat airbag locations. This list is also located in GlobalConnect in the Service Department Reference Library, titled "31820 Stock Sold VINs with Seat Airbag" (reference # GCUS-14-628).

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS