



05/11/2016

New Safety Recall Advanced Communication – S33051116

FCA US LLC (“FCA US”) announced a safety recall on certain 2007 through 2010 model year (JK) Jeep Wrangler vehicles.

Some of the above vehicles may have been built with a steering column clockspring that may ingest dust if the vehicle is subjected to extremely dusty environments. Dust inside the clockspring could compromise airbag circuit(s), cause illumination of the airbag warning light and/or a non-deployment of the driver airbag during a crash.

Non-deployment of the driver airbag, when deployment is required, could increase the risk of injury to the driver during a crash.

FCA US will conduct a voluntary safety recall to replace the steering column clockspring, steering wheel back cover, and steering column shrouds.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC