



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-1602
NHTSA RECALL NO. 16V-316
June, 2016**

TO: U.S. and Canadian Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar LLC, has decided that a defect that relates to motor vehicle safety exists in 2016-2017 model year Xpeditor chassis. These chassis were manufactured between 4 March 2016 and 21 April 2016 with non-sequential serial numbers in the range 222145 and 222800. Accordingly, a recall to address this issue is being initiated effective 30 June 2016.

**MODELS
AFFECTED:** Autocar Xpeditor MY 2016-2017

**COMPONENTS
AFFECTED:** Tab lock washer on rear axle wheel ends.

**SAFETY DEFECTS
AND POTENTIAL
RISKS:** The tab lock washers on the rear axle wheel ends may not have been properly bent over the outer spindle nut during assembly. If the tabs are not properly bent, the spindle nuts could loosen, and the wheel assembly could separate from the rear axle. Separation of the wheel from the rear axle may result in a vehicle crash.

**REPAIR
REQUIRED:** Remove the rear axle shaft and inspect the tab lock washer for properly bent tabs. If tabs are not properly bent, torque the spindle nut, check the wheel end play, and bend the tabs on the tab lock washer. Reinstall the axle shaft with a new gasket.

**REPAIR
AVAILABLE:** Parts and repair instructions will be available on 30 June 2016. VIN profiles in the Autocar Warranty System will also be updated to show the open recall on this date.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000