



TMS Toyota Customer Services
Product Quality and Service Support, Quality Compliance
Published September 7, 2016
Approved By: Tom Trisdale

Toyota Motor Sales, USA, Inc.
19001 South Western Avenue
Torrance, CA 90501
(310) 468-4000

To: All Toyota Dealer
From: Product Support Division

****Dealer Letter Now Available on TIS****

**Safety Recall G0S – Remedy Notice
Certain 2015 Model Year Yaris Vehicles
Front Shock Absorber Strut Bearing**

The Safety Recall G0S-Remedy dealer letter, FAQ and technical instructions are now available on TIS.

Refer to these documents on TIS for additional information.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.