

[Next Unread Message](#)**View Message**

<b>Sent on</b>	06	04	2016	<b>Expires on</b>	09	01	2016
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Campaign Administration
-------------	-------------------------

<b>Subject</b>	Stop Sale/Safety Recall: 2015-16 Odyssey, Pilot Fuel Tank Leak
----------------	--

DATE: June 4, 2016

TO: All Honda Sales, Service &amp; Parts Managers and Personnel

FROM: Campaign Administration

RE: Stop Sale/Safety Recall: 2015-16 Odyssey, Pilot Fuel Tank Leak

Yesterday, June 3, 2016, American Honda notified NHTSA of a **Safety Recall** affecting 15 units of model year 2015-16 Odyssey and 14 units of the 2016 Pilot to replace the fuel tank. **Any used units in dealer stock must be repaired per service bulletin, 16-051 *Safety Recall: 2015–16 Odyssey and 2016 Pilot Fuel Tank*, prior to sale.** Refer to your eResponsibility report or VIN inquiry to determine which units in your inventory are affected. American Honda Motor Co., Inc. expects to begin customer notification in early July 2016.

Note: Some vehicles affected by this campaign may be in your used vehicle inventory. Failure to repair a vehicle subject to a recall or campaign may subject your dealership to claims or lawsuits from the customer or anyone else harmed as a result of such failure. In addition, state law may provide American Honda with the right to seek indemnification in any such claim or lawsuit.

**Basic Problem**

Due to a vendor manufacturing error involving plastic welds, a small number of fuel tanks may develop a fuel leak over time. A fuel leak in the presence of an ignition source may increase the risk of a fire.

**Campaign Information**

Service bulletin 16-051, has been posted to the Service Information System as of June 4, 2016, and includes warranty, parts, and repair information related to the recall campaign.

**Parts Information**

Refrain from ordering for parts stock as there are limited vehicles in this campaign. Order a replacement fuel tank only after confirmation that a vehicle repair is needed.

**Warranty and Repair Information**

Warranty and repair information is detailed in service bulletin 16-051.

**Customer Notification**

American Honda expects to complete initial customer notification by early July, 2016.

As always, please be sure to check VIN status inquiry to determine if a particular VIN is affected by this recall.

Click [here](#) for a copy of bulletin 16-051.