



0985 N 900 W • Shipshewana, IN 46565
e-mail: kz@kz-rv.com • www.kz-rv.com
Phone: 260.768.4016 • Fax: 260.768.4017

IMPORTANT SAFETY RECALL

KZRV, L.P.

**NHTSA Recall Number 16V-432
Transport Canada Recall Number 2016-294**

Date: July 22, 2016

TO: KZRV Dealer

Problem

KZRV has decided that certain KZRV recreational vehicles. 2016-2017 Spree Model 337RES and 339RKS trailers ordered with an optional 12 cubic foot refrigerator were built with the refrigerator exhaust vent located in the wrong location. In addition, an internal baffle may also not be properly located. An improperly located vent location may cause the refrigerator compartment to overheat which would trigger the high temperature sensor and result in the refrigerator shutting down. If the high temperature sensor on the refrigerator fails to shut the refrigerator down there could be a risk of fire.

RANGE OF VEHICLES INVOLVED:

- 2016 thru 2017 Spree KZRV Travel Trailers

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair on the Spree model 337RES is 4 hours and on the Spree model 339RKS the time allowed is 9 hours.

SERVICE ACTION:

Install a larger refrigerator exhaust vent on the affected units.

encl. – Owners Letter, Repair instructions with parts list.

Mark Owens

Director of Service and Warranty Administration