



**ABOVE & BEYOND**

**SAFETY RECALL P086 – WARRANTY PROGRAM CODE  
CHANGE**

**SERVICE ALERT**

24-JUN-16

NO: SA16RE-01

SEC: RECALL

MKT.: CAN / USA

Please be advised that the Warranty Program Code for Safety Recall P086, *Driver Airbag Slow Deployment*, has been changed from 'Q598' to 'P086'. Retailers must submit any outstanding and future claims for this Safety Recall under the new Program Code.

Updated Service and Technical Bulletins reflecting this change will be published to InfoTrail and TOPIx shortly.