

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4181
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 1, 2016

Subject: 54180 02 – Safety Recall
Misrouted Fuel Line – Part Information Revised

Models: 2016 Buick Verano Equipped with 2.0L Turbo Engine (RPO LHU)

To: All Buick Dealers

This bulletin is being reissued to revise the part information section. Please discard all copies of bulletin 54180.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS