



IMPORTANT SAFETY RECALL

**AUTOCAR INDUSTRIES, LLC SAFETY RECALL ACTT-1601
NHTSA RECALL NO. 16V-599
TC RECALL NO. 2016-401
October, 2016**

TO: U.S. and Canadian Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar Industries LLC, has decided that a defect that relates to motor vehicle safety exists in 2016-2017 model year Xspotter chassis. These chassis were manufactured between 3 August 2015 and 21 April 2016 with non-sequential serial numbers in the range 219658 and 222100. Accordingly, a recall to address this issue is being initiated effective 7 October 2016.

MODELS Autocar Xspotter MY 2016-2017
AFFECTED:

COMPONENTS Steering Column
AFFECTED:

SAFETY DEFECTS The steering column internal shaft weld can break, potentially resulting in the separation
AND POTENTIAL of the steering wheel from the steering system. Separation of the steering wheel from
RISKS: the steering system results in loss of steering, increasing the risk of a vehicle crash.

REPAIR Inspect the steering column label lot number. If the lot number is 869501, the steering
REQUIRED: column must be replaced. If the lot number is not 869501, no further action is required.

REPAIR Parts and repair instructions will be available on 7 October 2016. VIN profiles in the
AVAILABLE: Autocar Warranty System will be updated to show the open recall on this date.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice
unless the recall remedy has been completed. Substantial civil penalties apply to
violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department
at warranty@autocartruck.com.

Sincerely,

AUTOCAR INDUSTRIES, LLC

ACF 00002 Rev. 000