



Innovation that excites

# SAFETY RECALL

# CAMPAIGN BULLETIN

## Maxima and Murano Anti-lock Braking System (ABS) Actuator Voluntary Safety Recall Campaign

Reference: PC482

Date: September 25, 2018

Attention: Dealer Principal, Sales, Service & Parts Managers

### UPDATE September 25, 2018

- **Campaign PC482 is no longer active**
  - Campaign PC482 has been superseded by PC649, R1807, and R1809
    - Any VINs subject to PC482 that received notifications, but were not inspected or remedied will be included in the new campaigns and will receive a new notification
- Please discard earlier versions of this bulletin.**

#### \*\*\*\*\* Part Return Information \*\*\*\*\*

Dealers should return all of the following parts to their PDC by **no later than September 30, 2018** using an **I-code**. **These parts are obsolete and should not be used for any repairs (including warranty or customer pay).**

- 47660-4RB1B
- 47660-5AA1C
- 47660-5AE1C
- 47660-9UC1B
- 47660-9UC1D

#### \*\*\*\*\*Claim Information \*\*\*\*\*

Retailers should submit any open claims for repairs performed under this campaign ID (PC482) by **October 5, 2018**. Submit a "CM" line claim using the following claims coding:

Campaign ("CM") I.D.	DESCRIPTION	OP CODE	FRT
PC482	Inspect anti-lock brake system (ABS) actuator serial number – <b>OK Condition</b>	PC4820	0.3 hrs
	Inspect anti-lock brake system (ABS) actuator serial number and replace ABS Control Unit – <b>Repair Condition</b>	PC4821	2.6 hrs.

#### Revision History:

Date	Announcement	Purpose
September 7, 2016	Original	New campaign announcement
October 28, 2016	Revision 1	TSB now available
November 30, 2016	Revision 2	Revised TSB and parts update
January 13, 2017	Revision 3	Revised TSB and additional vehicle handling instructions
September 1, 2017	Revision 4	Parts restriction ended
September 25, 2018	Revision 5	Campaign superseding to PC649, R1807, & R1809