

## View Message

<b>Sent on</b>	09	26	2016	<b>Expires on</b>	10	14	2016
<b>From</b>	Motorcycle National Field Service						
<b>Subject</b>	SERVICE BULLETINS: 2014-2015 Grom 125 #1 and NSS300 #1 Fuel Pump Replacement						

The Service Bulletins in support of the SAFETY RECALLS for certain model year 2014-2015 Grom125 motorcycles and NSS300/A scooters to replace the fuel pump is posted on *iN*.

## SERVICE BULLETINS

Service Bulletin Grom125 #1 has been revised to include an expanded model year and VIN range, revised parts information, as well as revised warranty claim information.

Service Bulletin NSS300 #1 has been revised to include an expanded model year and VIN range, revised repair procedure, revised parts information, as well as revised warranty claim information.

PARTS INFORMATION Redesigned remedy parts are available on open order for both campaigns.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact Motorcycle TechLine through TechLine Connect on *iN*, or call TechLine at (800) 421-1900, option 9; or contact your District Service Manager.

Thank you,  
American Honda Motor, Co., Inc.

Bradley Little  
Manager, National Field Service  
Motorcycle Division

Bulletin Number 16-0276