

View Message

| | | | | | | | |
|---------|--|----|------|------------|----|----|------|
| | | | | | | | |
| Sent on | 09 | 12 | 2016 | Expires on | 10 | 12 | 2016 |
| From | Motorcycle National Field Service | | | | | | |
| Subject | STOP SALE NOTICE: 2014-2015 NSS300/A and Grom125 | | | | | | |

September 12, 2016

Re: **STOP SALE NOTICE**

Dear Honda Dealer:

Honda is announcing a STOP SALE NOTICE of specific VINs for 2014 and 2015 model years NSS300/A scooters and Grom125 motorcycles to replace the fuel pump.

Honda has determined that the original remedy fuel pump used to repair 2014 models does not meet Honda durability standards. These same fuel pumps were used in certain model year 2015 vehicles which are now included in this STOP SALE.

Effective immediately, YOU MUST NOT SELL any affected NEW or USED 2014-2015 NSS300/A or 2014-2015 Grom125 vehicle until it is repaired according to the revised Service Bulletin procedure.

AFFECTED UNITS

2014-2015 NSS300/A: Certain VINs

2014-2015 Grom125: Certain VINs

- You are required to use *Unit Information* (effective September 14, 2016) on **iN** to determine if a specific VIN is affected by this STOP SALE.
- To manage your affected inventory, use *eResponsibility* Report (effective September 14, 2016).

SERVICE BULLETIN

American Honda intends to post revised Service Bulletins on **iN** in the near future.

At this time, DO NOT continue to perform any repairs under Service Bulletins NSS300 #1 and Grom125 #1.

PARTS INFORMATION

A redesigned remedy part is forthcoming.

CUSTOMER NOTIFICATION

AHM intends to mail customer letters as soon as possible, subject to State registration information.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact TechLine through *TechLine Connect* on **iN** or call your District Service Manager.

Sincerely,

American Honda Motor Co., Inc.

Bradley Little
 Manager, National Field Service
 Motorcycle Division

Bulletin #: 16-0267