

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4265
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 18, 2016

Subject: Safety Recall 16107-01
Accelerator Pedal Entrapment
Service Procedure Revised

Models: 2016 Chevrolet Low Cab Forward 3500/4500 Medium Duty
Trucks Equipped with 6.0L V-8 Engine

To: All General Motors Dealers

The service procedure has been revised. Please see the attached bulletin for details and discard all copies of 16107.

Vehicles involved in this recall were placed on stop delivery November 1, 2016. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS