



0985 N 900 W • Shipshewana, IN 46565  
www.livinlite.com

## **IMPORTANT SAFETY RECALL**

### **Livin Lite**

**NHTSA Recall Number 16V-865  
Transport Canada Recall Number 2016-589**

**Date: January 15, 2017**

**TO: Livin Lite Dealer**

#### **Problem**

Livin Lite has decided that certain 2017 Livin Lite recreational vehicles were not manufactured with the proper propane tubing in the cook top burner box. If not replaced, the rubber propane line could meet and result in a leak. This could result in a fire. The remedy is to install the correct copper tubing in the cook top.

#### **RANGE OF VEHICLES INVOLVED:**

- 2017 Livin Lite Recreational Vehicles

#### **WARRANTY REIMBURSEMENT:**

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 30 minutes.

#### **SERVICE ACTION:**

Install a 12" copper tube in the cook top burner box and retest the LP system.

encl. – Owners Letter, Repair Instructions

**Mark Owens**

Director of Service and Warranty Administration