



---

01/12/2017

## **Revised Safety Recall Advanced Communication – S89011217**

In December 2016, FCA US LLC (“FCA US”) announced a safety recall on certain 2016 model year (JC) Dodge Journey, (MK) Jeep Compass and Jeep Patriot vehicles equipped with a 2.0L or 2.4L engine.

Some of the above vehicles may have a crankshaft sensor and/or camshaft sensor electrical connector terminal(s) that were improperly manufactured. Improperly manufactured crankshaft and/or camshaft sensor electrical connector terminal(s) could result in an intermittent electrical connection. An intermittent electrical connection could cause an engine “no start” condition, an engine stall event while driving, and/or the illumination of the Malfunction Indicator Lamp (MIL). An engine stall event while driving could cause a crash without warning.

FCA US will conduct a voluntary safety recall to replace the crankshaft and/or camshaft electrical connector and terminals.

**VINs identified as being involved in this campaign are currently live and searchable under Recall S89.**

Dealers will be notified of the launch of this safety recall by way of established methods used in the past. **Remedy communication is estimated to be available in the 1<sup>st</sup> Quarter of 2017.**

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations  
FCA US LLC