



12/14/2016

New Safety Recall Advanced Communication – S89121416

FCA US LLC (“FCA US”) announced a safety recall on certain 2016 model year (JC) Dodge Journey, (MK) Jeep Compass and Jeep Patriot vehicles equipped with a 2.0L or 2.4L engine.

Some of the above vehicles may have a crankshaft sensor and/or camshaft sensor electrical connector terminal(s) that were improperly manufactured. Improperly manufactured crankshaft and/or camshaft sensor electrical connector terminal(s) could result in an intermittent electrical connection. An intermittent electrical connection could cause a “no start” condition, the engine to stall while driving, and/or the illumination of the Malfunction Indicator Lamp (MIL). An engine stall event while driving could cause a crash without warning.

FCA US will conduct a voluntary safety recall to replace the crankshaft and/or camshaft electrical connector and terminals.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past. This recall is estimated to launch in 1st Quarter of 2017.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC