



IMPORTANT SAFETY RECALL

This notice applies to your vehicle:

Date:

1**1**1*****ALL FOR AADC 481



VIN:

**Subject: Ducati Motorcycle:
 Model Year 2015-2017 Scrambler; Model Year 2016-2017 Scrambler Sixty2**

NHTSA Campaign I.D. Number: 16V891
Transport Canada Safety Recall I.D. Number: 2016613

Dealer Bulletin: SRV-RCL-16-004

Dear Ducati Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act & Canada Motor Vehicle Safety Act.

Ducati Motor Holding S.P.A. has decided that a defect which relates to motor vehicle safety exists in Model Year 2015-2017 Scrambler, and Model Year 2016-2017 Scrambler Sixty2 motorcycles. Our records indicate that you are the owner of a Ducati motorcycle affected by this safety recall campaign. Please take the time to read this letter and help us take the appropriate steps to ensure that your vehicle is operating properly.

What is wrong?

Ongoing quality testing on the motorcycles as manufactured, as well as analysis of field reports, has identified a potential safety issue affecting all Model Year 2015-2017 Scrambler, and Model Year 2016-2017 Scrambler Sixty2 motorcycles. Ducati has determined that on certain motorcycles, the threads of the side stand pivot bolt may be too short to engage in the locking nut, potentially allowing the side stand pivot to become loose. As a result, the side stand sensor switch may no longer detect the proper position of the stand. This could cause the motorcycle to fail to start while parked, or could cause the engine to stall while the motorcycle is in motion. Additionally, it may be possible to start the engine and begin riding with the stand down. These conditions could increase the risk of a crash causing injury and/or damage to property.



CAMBIO DE SEGURIDAD IMPORTANTE

Esta notificación aplica para su vehículo:

Date:

Modelo:

NIV:

**Asunto: Motocicleta Ducati:
 Scrambler modelos 2015-2017; Scrambler Sixty2 modelos 2016-2017**

Id. de campaña NHTSA Número: 16V891

Id. de cambio de seguridad de Transport Canada. Número: 2016613

Boletín del concesionario: SRV-RCL-16-004

Estimado propietario de Ducati:

Este aviso se le envía de acuerdo con la Ley nacional de Seguridad para vehículos automotores y tráfico y la Ley de seguridad de vehículos automotores de Canadá.

Ducati Motor Holding S.P.A. ha decidido que existe un defecto relacionado con la seguridad de los vehículos automotores en las motocicletas Scrambler modelos 2015-2017 y Scrambler Sixty2 modelos 2016-2017. Nuestros registros indican que usted es propietario de una motocicleta Ducati afectada por esta campaña de retiro de seguridad. Tómese el tiempo para leer esta carta y ayudarnos a tomar los pasos adecuados para asegurarse que su vehículo funciona correctamente.

¿Qué está mal?

Las pruebas continuas de calidad en las motocicletas fabricadas, así como los análisis de los informes de campo, han identificado un posible problema de seguridad que afecta todas las motocicletas Scrambler modelos 2015-2017 y Scrambler Sixty2 modelos 2016-2017. Ducati ha determinado que en ciertas motocicletas, las roscas del tornillo pivote del soporte lateral pueden ser muy pequeñas como para engancharse en la tuerca de bloqueo, permitiendo potencialmente que el pivote del soporte lateral quede suelto. Como resultado, el interruptor del sensor del soporte lateral puede dejar de detectar la posición adecuada del soporte. Esto podría causar que la motocicleta no arranque mientras está estacionada o que el motor se detenga mientras está en movimiento. Además, es posible arrancar el motor y empezar a conducirla con el soporte caído. Estas condiciones podrían aumentar el riesgo de un accidente que provoque lesiones o daños a la propiedad.



What will Ducati do?

To correct this condition, your authorized Ducati dealer will replace the side-stand pivot bolt with a new revised version that has a longer threaded portion. Additionally, the torque of the side-stand pivot bolt will be increased, and threadlock will be applied. The Dealer will perform this intervention at no cost to you for parts and labor. We request that you contact your authorized Ducati dealer and schedule an appointment, so that the required service can be performed without delay. To locate your nearest authorized Ducati dealer, please go to www.ducati.com, or www.canada.ducati.com , and select the "dealer locator" or you may call toll free from the U.S. 1-800-231-6696. Your dealer can complete the required service in less than one hour, if you have an appointment, though additional time may be required.

Federal regulations require that any lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Service Problem Help:

If you believe that your dealer has failed or is unable to perform the service within a reasonable period of time, please write to:

Ducati North America, Inc.
Attn: Customer Service
10443 Bandlely Drive
Cupertino, CA 95014

If you still cannot obtain satisfaction, you may file a complaint with:

For USA Customers:

National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Or call toll-free hotline at 1-888-327-4236 (TTY 1- 800-424-9153), or go to [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).

For Canadian Customers:

Please contact Ducati customer service at 1-888-391-5446 or for additional information about the recall you can contact Transport Canada at 1-800-333-0510.



¿Qué hará Ducati?

Para corregir esta condición, su concesionario Ducati autorizado sustituirá el tornillo pivote del soporte lateral por una nueva versión revisada que tiene una parte roscada más larga. Además, se aumentará el par de torsión del tornillo pivote del soporte lateral y se aplicará un bloqueador de rosca. El concesionario realizará esta intervención sin costo alguno por las piezas y mano de obra. Le solicitamos que se comunique con su concesionario local autorizado de Ducati y programe una cita de manera que se pueda realizar el servicio requerido sin demora. Para localizar a su concesionario Ducati más cercano, diríjase a www.ducati.com, o www.canada.ducati.com y seleccione el "localizador de concesionario" o puede llamar gratis desde EE. UU. al 1-800-231-6696. Su concesionario puede completar el servicio requerido en menos de una hora, si tiene una cita, aunque puede ser necesario tiempo adicional.

Las regulaciones federales requieren que cualquier arrendador que reciba este aviso de cambio debe enviar una copia de este aviso al arrendatario dentro de diez días.

Ayuda del problema de servicio:

Si considera que su concesionario ha fallado o no puede realizar el servicio dentro de un período razonable, escriba a:

Ducati North America, Inc.
Attn: Customer Service (Servicio al cliente)
10443 Bandley Drive
Cupertino, CA 95014

Si no se soluciona el problema, puede presentar una queja con:

Para clientes de EE. UU.:

National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, D.C. 20590

O llamar a la línea gratuita al 1-888-327-4236 (TTY 1- 800-424-9153) o ir a [HTTP://WWW.SAFERCAR.GOV](http://WWW.SAFERCAR.GOV).

Para clientes canadienses:

Comuníquese con servicio al cliente de Ducati al 1-888-391-5446 o para obtener información adicional acerca del cambio, puede comunicarse a Transport Canada al 1-800-333-0510.



TREADACT CUSTOMER REIMBURSEMENT PLAN

If you have paid for the repair described in the attached letter, and you would like to be considered for reimbursement, please contact your authorized Ducati dealer. Expenses from repair facilities outside of the authorized Ducati dealer network will be considered; however, the procedure must meet Ducati North America's standards.

Your authorized Ducati retailer will request a copy of your owner notification letter, as well as, a copy of your previously paid invoice. They inspect the vehicle, if still in your possession, prior to submitting a claim on your behalf to Ducati North America, Inc. for reimbursement.

Please note the following:

Only a repair subject of this safety recall campaign is reimbursable. Ducati North America, Inc will not reimburse consequential expenses such as towing, rental, accommodations, and damage repairs.

We recommend that your authorized Ducati dealer be your primary contact on this issue. We anticipate that your authorized Ducati dealer will be able to answer any questions that you may have regarding your qualifications for reimbursement of a previous repair; however, our Customer Relations Dept. may be contacted at 408-253-0499 for any special assistance required.

We regret any inconvenience to you from this action; however, your safety and satisfaction are important to us. We request that you bring your Ducati motorcycle to your nearest authorized Ducati dealer at your earliest convenience.

Thank you for riding Ducati.

Sincerely,

Ducati North America
Service Department



PLAN DE REEMBOLSO DEL CLIENTE TREADACT

Si ha pagado por la reparación que se describe en la carta adjunta y le gustaría que se le tomara en cuenta para el reembolso, comuníquese con su concesionario Ducati autorizado. Los gastos de las instalaciones de reparación fuera de la red de concesionarios Ducati autorizados se tendrán en cuenta; sin embargo, el procedimiento debe cumplir con los estándares de Ducati North America.

Su minorista Ducati autorizado solicitará una copia de su carta de notificación de propietario, así como una copia de su factura pagada previamente. Ellos inspeccionarán el vehículo, si aún está en su posesión, antes de enviar un reclamo en su nombre a Ducati North America, Inc. para reembolso.

Tenga en cuenta lo siguiente:

Solo un asunto de reparación de esta campaña de retiro de seguridad es reembolsable. Ducati North America, Inc no reembolsará los gastos consecuenciales como remolque, alquiler, alojamiento y reparaciones de daños.

Recomendamos que su concesionario autorizado Ducati sea su contacto primario en este problema. Anticipamos que su concesionario Ducati autorizado podrá responder cualquier pregunta que pueda tener en relación con sus calificaciones para el reembolso de una reparación anterior; sin embargo, puede comunicarse a nuestro Dept. de relaciones con los clientes al 408-253-0499 para cualquier asistencia especial que necesite.

Lamentamos cualquier molestia para usted a causa de esta acción; sin embargo, su seguridad y satisfacción son importantes para nosotros. Le solicitamos que lleve su motocicleta Ducati a su concesionario Ducati autorizado más cercano tan pronto como le sea posible.

Gracias por conducir Ducati.

Atentamente,

Ducati North America
Departamento de servicio