



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department



IMPORTANT SAFETY RECALL

September, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number:



Dear Maserati Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect which relates to motor vehicle safety exists in model year 2015 Maserati Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles may have been manufactured with a right and/or left-hand side front wheel bearing that was insufficiently hardened. An insufficiently hardened front wheel bearing will not be able to withstand high heat transfers which is normally experienced in certain driving conditions, especially if the vehicle is carrying heavier loads, and can potentially fail, increasing the risk of a crash.

The remedy is the inspection of the right and left-hand side front wheel bearings on your vehicle, and based on the inspection, one side or both the right and left-hand side front wheel bearings on the affected vehicles will be replaced. The remedy will be performed free of charge. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed on your automobile. The repairs, depending on if one or both front wheel bearings require replacement, may take up to 2 hours to complete. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

Continued on next page



IMPORTANT SAFETY RECALL

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.
250 Sylvan Avenue
Englewood Cliffs, NJ 07632
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku
Manager, Certification & Compliance Department