



IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with the VIN(s) indicated on the enclosed owner response cards.

**AUTOCAR, LLC SAFETY RECALL ACX-1605
NHTSA RECALL NO. 16V-852
January, 2017**

Dear Autocar Truck Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has decided that a defect which relates to motor vehicle safety exists in 2012-2016 model year Xpeditor chassis. These chassis were manufactured between 6 September 2011 and 1 October 2015, with non-sequential serial numbers in the range 213189 through 221130. Our records indicate that your vehicle was manufactured within this time period and may contain the defect described herein.

- MODELS AFFECTED:** Autocar Xpeditor 2012-2016
- COMPONENTS AFFECTED:** Hybrid power drive unit cradle mounting bolts.
- SAFETY DEFECTS AND POTENTIAL RISKS:** Mounting bolts for the hybrid power drive unit cradle may have been improperly torqued. If the mounting bolts for the cradle are not properly torqued, the bolts may loosen and the power drive unit and drive shaft may become partially or completely detached from the underside of the vehicle, increasing the risk of a crash.
- REPAIR REQUIRED:** Remove and inspect mounting bolts one at a time for damage. Replace any damaged bolts with new bolts. Install/reinstall all bolts with thread lock agent and torque to proper specification.
- TIME REQUIRED FOR THE REPAIR:** The labor time to repair your vehicle is 2.0 hours.
- WHAT YOU SHOULD DO:** To have your vehicle repaired, contact your local authorized Autocar service site or email warranty@autocartruck.com.
- PRIOR REPAIRS:** If you have previously paid for repairs relating to this recall you may be entitled to recover the amount you paid for those repairs. Submit a copy of all documentation supporting your claim to Autocar at the address set forth below in the "Assistance" section.

ACF 00002 Rev. 000



**NOTICE
REGARDING
LEASED
VEHICLES:**

If you are a Lessor (as defined below) of a vehicle that is affected by this notice, you are obligated under federal law to provide a copy of this Notice to the lessee of such vehicle within 10 days of your receipt of this Notice. Further, you must maintain a record, which identifies the lessee(s) to whom you send a copy of this Notice, the date you send the Notice and the VIN of the vehicle that you have leased to the lessee(s).

For purposes of this Notice, the term "Lessor" means a person or entity that is the owner, as reflected on the vehicle's title, of any five or more leased vehicles, as of the date of this Notice.

**OWNER RECALL
RESPONSE
CARD:**

The enclosed Owner Recall Response Card identifies your vehicle. Please complete this postage-paid card and return it to Autocar. If you do not own, have sold or have traded the vehicle identified on the card, please indicate that on the postage-paid card and return it to Autocar.

ASSISTANCE:

If you need assistance with this recall, call our toll-free numbers below or write to Autocar at:

Autocar, LLC
Service & Warranty Departments
551 S. Washington St.
Hagerstown, Indiana 47346
888-218-3611 (Toll Free)
877-973-3486 (Toll Free)

You may also submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington, DC 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 800-424-9153); or go to <http://www.safercar.gov>.

We regret any inconvenience this recall may cause, but we hope you recognize Autocar's concern for your safety and satisfaction with your vehicle.

Sincerely,

AUTOCAR, LLC