




## IMPORTANT SAFETY RECALL INFORMATION

December 20, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number: 

Dear Maserati Customer:

This notification is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect that relates to motor vehicle safety exists in model year 2017 Maserati Quattroporte and Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles were manufactured with a rear differential unit pinion nut that was not torqued correctly. A loose pinion nut will result in a reduction or total loss of axial force, as well as insufficient orientation of the pinion itself. A loose pinion nut will potentially have an adverse effect on noise, vibration and harshness (NVH) performance, reduced gear, and bearing life, and can cause a differential fluid leak at the pinion seal. In the most severe cases of a loose pinion nut, axial loads could force the pinion into a differential gear binding condition, which can result in blocking the rotation of the ring gear, and potentially locking the rear wheels, thereby increasing the risk of a vehicle crash.

The proposed remedy is a check of the rear differential unit pinion nut torque and, if necessary, the replacement of the rear differential unit. The remedy will be performed free of charge to the vehicle owner. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed to your automobile. The remedy is expected to take approximately 1 hour 15 minutes for inspection, and 3 hours if replacement of the differential is necessary. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

*Continued on next page*



## IMPORTANT SAFETY RECALL INFORMATION

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.  
250 Sylvan Avenue  
Englewood Cliffs, NJ 07632  
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.


Sincerely,

Daniel Doku  
Manager, Certification & Compliance Department



## IMPORTANT SAFETY RECALL INFORMATION

December 20, 2016



This Notice Applies To Your Vehicle, Vehicle Identification Number: 

Dear Maserati Customer:

This notification is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect that relates to motor vehicle safety exists in model year 2017 Maserati Quattroporte and Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles were manufactured with a rear differential unit pinion nut that was not torqued correctly. A loose pinion nut will result in a reduction or total loss of axial force, as well as insufficient orientation of the pinion itself. A loose pinion nut will potentially have an adverse effect on noise, vibration and harshness (NVH) performance, reduced gear, and bearing life, and can cause a differential fluid leak at the pinion seal. In the most severe cases of a loose pinion nut, axial loads could force the pinion into a differential gear binding condition, which can result in blocking the rotation of the ring gear, and potentially locking the rear wheels, thereby increasing the risk of a vehicle crash.

The proposed remedy is a check of the rear differential unit pinion nut torque and, if necessary, the replacement of the rear differential unit. The remedy will be performed free of charge to the vehicle owner. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed to your automobile. The remedy is expected to take approximately 1 hour 15 minutes for inspection, and 3 hours if replacement of the differential is necessary. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

*Continued on next page*



## IMPORTANT SAFETY RECALL INFORMATION

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.  
250 Sylvan Avenue  
Englewood Cliffs, NJ 07632  
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku  
Manager, Certification & Compliance Department



## IMPORTANT SAFETY RECALL INFORMATION

December 20, 2016

[REDACTED]

This Notice Applies To Your Vehicle, Vehicle Identification Number: [REDACTED]

Dear Maserati Customer:

This notification is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Maserati S.p.A. and MNA have decided that a defect that relates to motor vehicle safety exists in model year 2017 Maserati Quattroporte and Ghibli vehicles.

Maserati S.p.A. and MNA have determined that the above described vehicles were manufactured with a rear differential unit pinion nut that was not torqued correctly. A loose pinion nut will result in a reduction or total loss of axial force, as well as insufficient orientation of the pinion itself. A loose pinion nut will potentially have an adverse effect on noise, vibration and harshness (NVH) performance, reduced gear, and bearing life, and can cause a differential fluid leak at the pinion seal. In the most severe cases of a loose pinion nut, axial loads could force the pinion into a differential gear binding condition, which can result in blocking the rotation of the ring gear, and potentially locking the rear wheels, thereby increasing the risk of a vehicle crash.

The proposed remedy is a check of the rear differential unit pinion nut torque and, if necessary, the replacement of the rear differential unit. The remedy will be performed free of charge to the vehicle owner. Since your vehicle is among those that may be affected by the above condition, we ask you to contact any Authorized Maserati Dealer in order to arrange for this recall action to be performed to your automobile. The remedy is expected to take approximately 1 hour 15 minutes for inspection, and 3 hours if replacement of the differential is necessary. Please plan, however, to leave your vehicle with the dealership to allow the dealer some flexibility for scheduling your repairs. By the time you receive this recall notification letter, the Authorized Maserati Dealers will have been supplied with the necessary instructions and components to perform the recall.

*Continued on next page*



## IMPORTANT SAFETY RECALL INFORMATION

If the dealer fails or is unable to make the necessary repairs free of charge within a reasonable time, or if you have any problem obtaining the needed repair, you should inform the national headquarters of Maserati North America, Inc., at:

Maserati North America, Inc.  
250 Sylvan Avenue  
Englewood Cliffs, NJ 07632  
(201) 510-2369 (Consumer Relations)

If you believe that Maserati has failed to remedy the defect described in this letter free of charge to you and within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration U.S. Department of Transportation, 1200 New Jersey Avenue, S.E., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten working days. If you no longer own this vehicle or your address has changed, **please complete the enclosed prepaid yellow card and return it to Maserati North America, Inc.**

We apologize for any inconvenience this may cause you.

Sincerely,

Daniel Doku  
Manager, Certification & Compliance Department