



YAMAHA MOTOR CORPORATION, U.S.A. 6555 Katella Avenue, Cypress, CA 90630-5101 800-962-7926

IMPORTANT SAFETY RECALL NOTICE

This notice applies to your vehicle, VIN XXXXXXXXXXXXXXXXXXXX

December 27, 2016

Dear Yamaha Owner:

Campaign 990111

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Yamaha Motor Corporation, U.S.A. has decided that a defect that relates to motor vehicle safety exist in certain 2015-2016 model XC155 ("Smax") scooters. Our records indicate that you own the affected scooter shown above.

The reason for this recall: In affected scooters, the speed sensor lead wire clamping is insufficient to stabilize the lead wires during turning and front suspension action. This could allow the sensor lead wires to fatigue and break. If the speed sensor lead wires break, the speedometer will stop working.

What Yamaha and your dealer will do: To correct this defect, your authorized Yamaha dealer will replace the speed sensor assembly with one of a different design that prevents a change in its position. The procedure takes approximately 40 minutes to do but be aware that your Yamaha dealer may need to keep your scooter longer. There will be no charge to you for this procedure.

What you should do now: Please call your Yamaha dealer to make a service appointment to have this procedure performed. At that same time, you can find out how long they expect to keep your scooter for this service. Although not necessary, please take this letter with you when you take in your scooter.

You should not ride your affected scooter shown above until this modification is performed.

If you are unable to return to the Yamaha dealer who sold you the scooter, this service will be performed by any authorized Yamaha scooter dealer. For the name of a dealer near you, call 1-800-88-YAMAHA or visit the Yamaha web site at www.yamaha-motor.com.

If you have had this repair performed before you received this letter, you may be entitled to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this repair. For more information, contact Yamaha Customer Relations at 1-800-962-7926.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you need help: If, after contacting your dealership, you have questions or concerns which the dealership is unable to answer, please write to:

Yamaha Motor Corporation, U.S.A.
Customer Relations Department
P.O. Box 6555
Cypress, CA 90630

Or call: 1-800-962-7926

If, after contacting Yamaha Customer Relations, you are still not satisfied that we have done our best to remedy the situation without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>. Refer to campaign 16V892.

If you no longer own this Yamaha: If you have sold your scooter to another party, please call us toll-free at 1-800-962-7926 with the name and address of the new owner, along with the VIN serial number shown above.

We're sorry to cause you any inconvenience, but we are sincerely concerned about your safety and continued satisfaction with our products. Thank you for giving your attention to this important matter.

Sincerely,
Customer Support Group
Yamaha Motor Corporation, U.S.A.