

**From:** [Broadcast Messaging System](#)  
**To:** [DL-BMS Message Monitors](#)  
**Subject:** Recall Campaign 16V-071: Driver-Side Front Air Bag Module  
**Date:** Thursday, February 11, 2016 4:31:30 PM

Publish Date: February 11, 2016  
From: Technical Service  
Expiration Date: February 25, 2016

DCSnet Message  
**Urgent**



**Subject: Recall Campaign 16V-071: Driver-Side Front Air Bag Module**

**Message Recipients: General Managers, Sales Managers, Service and Parts Managers, Service Managers, Shop Foremen, Service Technicians**

**Message Text:**

BMW AG is conducting a Voluntary Safety Recall involving Driver-Side Front Air Bag Module on certain BMW vehicles that are equipped with non-desiccated PSDI-5 inflators. These vehicles, covering model years 2006-2015 have not been part of earlier Takata-related air bag recalls. There are approximately 840,000 vehicles in the US.

As a follow-up to our announcement last week regarding the above Recall, it has been assigned number 16V-071. We are currently verifying all the affected VINs and within the next 72 hours, you will be able to identify which vehicles are affected via DCS Warranty Vehicle Inquiry or ISPA Light. We will provide you with more information regarding the repair process and parts availability as soon as possible. For additional information, please reference the attached SI B65 04 16, Q&A and Legal Recall notification.

Sincerely, Eugene Aton, Technical Service

Attachments:

-  [GA\\_B650416\[8167bb05\].pdf](#)
-  [B650416\\_Recall\\_Notice\[8167b9bb\].pdf](#)
-  [B650416\\_QA\[8167b9ba\].pdf](#)
-  [GA\\_B650416\[8167bb05\].pdf](#)
-  [B650416\\_Recall\\_Notice\[8167b9bb\].pdf](#)
-  [B650416\\_QA\[8167b9ba\].pdf](#)

Recipients: BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, All Departments, All Personnel  
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel