

September 23, 2016

# IMPORTANT SAFETY RECALL

***This notice applies to your vehicle;  
The VINs are listed on the back of this page***

Subject: Safety Recall 216-A Marmon –Herrington Axle Loose Flange Yoke Assembly Nuts  
NHTSA # 16V-066  
EXPIRATION DATE: NONE

216-A - 5

USA Customer  
USA Address  
USA City, State, Zip

**SECOND NOTICE**

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain year model 2015 and 2016 vehicles built between August 27, 2014 and June 5, 2015 that were manufactured with Marmon-Herrington axles. Your vehicle has been identified as having a Marmon-Herrington axle. On these vehicles equipped with a Marmon-Herrington axle, the hex nuts on the flange yoke assembly may not be torqued to specification.

If the hex nuts are not tightened to specification, the driveshaft may disconnect from the drive axle, resulting in a loss of propulsion and increasing the risk of a crash.

<b><i>The problem is...</i></b>	Loose hex nuts/bolts on the flange yoke assembly
<b><i>Correction...</i></b>	Inspect and tighten any loose nuts to proper torque
<b><i>What you must do ...</i></b>	Contact your dealer immediately to schedule an appointment

Peterbilt has initiated a recall to remedy the defect free of charge. To find your nearest Peterbilt dealer, please visit Dealer Locator at [www.Peterbilt.com](http://www.Peterbilt.com). This repair should take approximately 1.0 hours labor, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.


If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Peterbilt Motors Company, 1700 Woodbrook St. Denton, TX 76205, Attn: Quality Services Department, phone 940-591-4220.

If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Doug Gunter  
Director of Warranty  
Peterbilt Motors Company