



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

March 2017

RE: 2003-2008 Pilot
NHTSA Recall 16V-344

IMPORTANT

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear JOHN Q SAMPLE:

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. In certain 2003-2008 Honda Pilot vehicles, the passenger's front airbag inflator could produce excessive internal pressure upon deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator to rupture (break apart). In the event of an inflator rupture, metal fragments could pass through the airbag cushion material possibly causing serious injury or fatality to you or others in the vehicle. A prior rupture like this resulted in serious injury.

What will Honda do?

Honda will replace your vehicle's passenger's front airbag inflator **free of charge**. Call any authorized Honda dealer and make an appointment to have your vehicle repaired.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact Honda Automobile Customer Service at 1-888-234-2138. You may also find this information at www.Hondacars.com.

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #16-047

KA2