

IMPORTANT: SAFETY RECALL REMINDER

In September 2016, we notified you of a Safety Recall involving the fuel pump on your GROM 125 motorcycle. At the time, we advised owners of the following:

Honda has decided that a defect which relates to motor vehicle safety exists in certain 2014-2015 model year GROM 125 motorcycles. The fuel pump inlet cover (made of resin) may swell and interfere with the rotation of the fuel pump impeller, causing the fuel pump to stop working. If the impeller is unable to rotate properly, it may cause the engine to not start or stall while riding. An engine stall while riding increases the risk of a crash.

According to our records, you have not yet had your affected vehicle repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If your vehicle has already been repaired, or if you no longer own this vehicle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.
Motorcycle Division**