



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

February 2018

RE: 2017 Ridgeline
NHTSA Recall 16V-888

This notice applies to your vehicle:

IMPORTANT

- **Your vehicle is included in a safety recall and you should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service for free.**

Dear

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. Due to a manufacturing error, the rear wiring harness installed in your truck may allow for moisture entry. Moisture may flow through the rear wiring harness and corrode an electrical connection terminal that controls certain rear drivetrain functions. This corrosion can result in the Vehicle Stability Assist (VSA) system falsely detecting a malfunction and will decrease engine torque or apply brakes to the rear wheel(s). The unexpected and unnecessary application of brake assist while driving may increase the risk of a crash.

What will Honda do?

Call any authorized Honda dealer to have your truck's rear wiring harness and rear drivetrain components repaired or replaced, as necessary, **for FREE**.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda's Customer Support & Campaign Center at 1-888-234-2138. You may also find this information at www.hondacars.com.

We apologize for any inconvenience this safety recall may cause you.

Sincerely,

American Honda Motor Co., Inc.

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

FOR DEALER USE ONLY: REFERENCE SVC BULLETIN #16-093

KD3