

May 4, 2016
FL702A
NHTSA #16V-121

**Notice of Submission of Defect Information Report/Defect Information Notice
and Interim Notification**
Subject: FCCC XCP Chassis Power Steering Hoses

Daimler Trucks North America has determined that a safety related defect exists in certain chassis manufactured by Freightliner Custom Chassis Corporation and delivered to your company. As the incomplete vehicle manufacturer of these products, Daimler Trucks North America is unable to provide the National Highway Traffic Safety Administration and/or Transport Canada with the information necessary to fully describe the vehicles potentially containing this defect as required by Title 49 Code of Federal Regulations Part 573.6(c)(2) and/or Motor Vehicle Safety Regulations Section 15(1)(b). Your company may have an obligation to report this information.

The attached Defect Information Report and Defect Information Notice were filed with the appropriate government agencies. Please refer to these notices for details regarding the nature of the defect, the remedy. Daimler Trucks North America will be conducting this recall and filing the quarterly reports required by Title 49 CFR §573.7 and/or MVSr §15(3). Repairs will be performed by authorized Daimler Trucks North America repair facilities.

A list of potentially affected vehicles delivered to you is included.

Daimler Trucks North America has begun notifying its dealers and customers of the upcoming recall. A remedy without charge will soon be available.

Your company may have an obligation to notify its dealers, distributors, and customers of this recall under Title 49 Code of Federal Regulations Part 577.13 and/or Motor Vehicle Safety Act Section 10(1).

If you have questions regarding this notice, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure