



**Toyota Motor Engineering &
Manufacturing North America, Inc.**

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

January 9, 2018

AMENDED DEFECT INFORMATION REPORT (16V340)

This supplements Toyota's Part 573 Report (16V-340) concerning the Takata passenger inflator issue on certain Toyota, Scion, Lexus, and Pontiac Vibe vehicles.

As discussed with the Agency on December 13, 2017, the number of involved vehicles is amended (increased) to reflect zone assignment changes as a result of updated vehicle registration information obtained during the fourth quarter of 2017. The additional vehicles come from the population originally identified to be subject to Takata's DIR of December 31, 2017, according to the Second Amendment to the Coordinated Remedy Order, and that have since moved between zones (e.g. 2010MY Zone B moved to Zone A).

Total Number of Vehicles Potentially Involved:

Toyota Scion xB	:	96,940
Toyota Corolla	:	605,701
Toyota Corolla Matrix	:	46,247
Toyota Yaris	:	343,594
Toyota 4Runner	:	49,520
Toyota Sienna	:	88,921
Lexus IS250/350	:	206,734
Lexus IS250C/350C	:	13,540
Lexus IS-F	:	3,805
Lexus ES350	:	259,986
Lexus GX460	:	13,960
Pontiac Vibe	:	20,975
Total	:	1,749,923