

**NISSAN GROUP  
OF NORTH AMERICA**



---

**Nissan North America, Inc.**

One Nissan Way  
Franklin, TN 37067

Mailing Address:  
PO Box 685001  
Franklin, TN 37068

July 22, 2016

Mr. Gregory K. Rea  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
Attn: Recall Management Division (NVS-215)  
Room W48-302  
1200 New Jersey Avenue, SE  
Washington, D.C. 20590

Dear Sir:

We are enclosing an update to a Defect Information Report (16V-349) dated July 7, 2016. This report updates the model information in sections 2 and 3.

Nissan will notify vehicle owners by first class mail. Interim owner notification will be completed within 60 days of May 23, 2016. Nissan has already notified dealers. Nissan will notify owners again when the final remedy is available. Your office will be provided with an update on the remedy parts availability and copies of both the interim and final Part 577 owner notification.

Very truly,

A handwritten signature in black ink, appearing to read "Derek Latta".

Derek Latta  
Manager,  
Technical Compliance

Encl.

## **DEFECT INFORMATION REPORT**

1. Manufacturer:

Nissan Motor Co., LTD  
Nissan Mexicana, S.A. de C.V. Aguascalientes plant  
Nissan Mexicana, S.A. de C.V. Civac plant

2. Vehicles Potentially Involved:

<b><u>Model</u></b>	<b><u>Dates of Manufacture</u></b>
MY 2003-2008 Infiniti FX	May 13, 2003 to March 3, 2008
MY 2003-2004 Infiniti I35	May 8, 2003 to August 2, 2004
MY 2006-2010 Infiniti M	August 2, 2004 to January 7, 2010
MY 2007-2011 Nissan Versa	May 8, 2006 to July 2, 2011

The vehicles subject to this report are equipped with non-desiccated Takata inflators, in accordance with the schedule set forth in Paragraph 14 of the Amended Takata Consent Order EA15-001, that are not already subject to ongoing recalls. More specifically, the subject vehicles are either equipped with PSPI-6 passenger air bag inflators, or equipped with PSPI passenger air bag inflators that are not already subject to Recalls 15V-287 and 15V-226. (All vehicles equipped with non-desiccated SPI passenger air bag inflators are already subject to Recall 15V-287).

The name and address of the front passenger air bag inflator supplier is:

TK HOLDINGS INC.  
2500 Takata Drive  
Auburn Hills, MI 48326  
Phone: 248-373-8040  
Fax: 248-373-2897

3. Total Number of Vehicles Potentially Involved:

Approximately 413,852 vehicles shown in the table below:

<b><u>Make/Model</u></b>	<b><u>Number of Vehicles</u></b>	<b><u>Inflator Type</u></b>
MY 2003-2008 Infiniti FX	80,109	PSPI
MY 2003-2004 Infiniti I35	9,797	PSPI
MY 2006-2010 Infiniti M	76,110	PSPI
MY 2007-2011 Nissan Versa	247,836	PSPI-6

4. Percentage of Vehicles Estimated to Actually Contain the Defect:

## Unknown

To date, there are no known incidents of Nissan vehicles equipped with PSPI inflators. Also, there are no improper deployments of PSPI inflators (recovered from Nissan vehicles in the United States that are not already subject to existing recalls) in laboratory testing conducted by Takata (0 out of 3487 subject PSPI inflators tested).

To date, there are no known field incidents of Nissan vehicles equipped with PSPI-6 inflators. Nissan recently began an in-use PSPI-6 collection activity in Florida. To date, 352 PSPI-6 inflators have been subjected to laboratory testing by Takata and 6 out of 352 inflators deployed abnormally.

### 5. Description of the Defect:

According to Takata Defect Reports 16E-4200, 16E-4300 and 16E-4400, Takata has determined that a defect related to motor vehicle safety may arise in some of the subject ammonium nitrate inflators due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures and high temperature cycling. Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

### 6. Chronology of Principal Events:

May 4, 2016 – NHTSA issued an Amended Takata Consent Order EA15-001 requiring Takata to submit defect reports pertaining to non-desiccated inflators that are not already subject to ongoing recalls on a rolling basis prioritized by risk as set forth in the schedule in the Amended Takata Consent Order.

May 16, 2016 – As specified in the Amended Takata Consent Order, Takata submitted Defect Information Reports 16E-4200, 16E-4300 and 16E-4400.

May 17, 2016 – Based on the information in the Takata Defect Information Report and out of abundance of caution, Nissan decided to conduct a safety recall on the subject vehicles in accordance with the schedule set forth in Paragraph 14 of the Amended Takata Consent Order.

Nissan received the updated VIN information from Polk, and amended the 573 report for Recall 16V-349 Report on July 7, 2016.

### 7. Description of Corrective Action:

Nissan will notify vehicle owners by first class mail. Interim owner notification will be completed within 60 days of May 23, 2016. Dealers have been notified. Nissan will notify owners again when the final remedy is available. Your office will be provided with an update on the remedy parts availability and copies of both the interim and final Part 577 owner notification. Nissan will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy.

8. Copy of Notices:

Copies of all notices will be provided to NHTSA as they become available.