



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

January 18, 2017

Ms. Janet Anderson  
McLaren Automotive Incorporated  
750 3rd Ave  
Suite 2400  
New York, NY 10017

NEF-150TB  
17V-005

**Subject:** Passenger Frontal Air Bag Inflator May Rupture

Dear Ms. Anderson:

This letter serves to acknowledge McLaren Automotive Incorporated's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

MCLAREN/MP4-12C SPIDER/2012

**Mfr's Report Date:** January 9, 2017

**NHTSA Campaign Number:** 17V-005

**Components:**

AIR BAGS:PASSENGER SIDE FRONTAL

**Potential Number of Units Affected:** 359

**Problem Description:**

McLaren Automotive Incorporated (McLaren) is recalling certain 2012 MP4-12C vehicles originally sold, or ever registered, in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina and Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the front air bags, these inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

**Consequence:**

An inflator rupture may result in metal fragments striking the vehicle occupants resulting in serious injury or death.

**Remedy:**

McLaren will notify owners, and dealers will replace the air bag inflators, free of charge. Remedy parts are not currently available. McLaren will send a letter to the affected owners to notify them of the recall and will mail a follow up letter when remedy parts are available. Owners may contact McLaren customer service at 1-646-429-8916.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which the remedy-available notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian".

Jennifer Timian  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement