



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

October 16, 2017

Mr. John McDonald
Maserati North America, Inc.
1 Chrysler Dr.
Auburn Hills, MI 48326

NEF-150SM
17V-610

Subject: Fuel Pump may Fail and cause Stall

Dear Mr. McDonald:

This letter serves to acknowledge Maserati North America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MASERATI/QUATTROPORTE/2015-2017

Mfr's Report Date: September 29, 2017

NHTSA Campaign Number: 17V-610

Components:

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 439

Problem Description:

Maserati North America, Inc. (Maserati) is recalling certain 2015-2017 Quattroporte GTS vehicles equipped with a V8 3.8 liter engine. A resistor in the low pressure fuel pump resistor may fail, causing a loss of engine power or a stall.

Consequence:

A stall can increase the risk of a crash.

Remedy:

Maserati will notify owners, and dealers will replace the fuel pump resistor cable assembly, free of charge. The recall is expected to begin November 13, 2017. Owners may contact Maserati customer service at 1-201-510-2369. Maserati's number for this recall is 359.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with the first name being the most prominent.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement