



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

November 6, 2017

Mr. Michael Scott
Daimler Vans USA, LLC
303 Perimeter Center North
Atlanta, GA 30346

NEF-150KS
17V-650

Subject: Incorrect Load Capacity on Label/Part 567

Dear Mr. Scott:

This letter serves to acknowledge Daimler Vans USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/SPRINTER 2500/2016
MERCEDES BENZ/SPRINTER 3500/2016

Mfr's Report Date: October 16, 2017

NHTSA Campaign Number: 17V-650

Components:

EQUIPMENT:OTHER:LABELS

Potential Number of Units Affected: 2

Problem Description:

Daimler Vans USA, LLC (DVUSA) is recalling certain 2016 Mercedes-Benz Sprinter 2500 and 3500 vehicles. The label on the B-pillar may state a higher maximum vehicle load capacity than the vehicle is designed for. As such, these vehicles fail to comply with the requirements of 49 CFR Part 567, "Certification."

Consequence:

If the load capacity information is incorrect on the label, the vehicle may be overloaded, increasing the risk of a crash.

Remedy:

DVUSA will notify owners, and dealers will check the label and replace it if necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact DVUSA customer service at 1-877-762-8267.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian".

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement