

**Recall Quarterly Report****17V-051**

**Manufacturer Name :** Toyota Motor Engineering & Manufacturing  
**NHTSA Recall No. / MFR Recall No. :** 17V-051 /H0C  
**Recall Subject :** Rear Step Bumper May Break after Damage to Bracket  
**Owner Notification Beginning Date :** APR 21, 2017  
**Owner Notification End Date:** MAY 05, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 27, 2017	2017-2	72,847	25,494	6,938	0

This Document Last Updated : JUL 28, 2017

**Definitions :**

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.