

**Recall Quarterly Report****17V-081**

**Manufacturer Name :** Mercedes-Benz USA, LLC.  
**NHTSA Recall No. / MFR Recall No. :** 17V-081 /  
**Recall Subject :** Upper Control Arm Connecting Bolt may be Loose  
**Owner Notification Beginning Date :** MAR 28, 2017  
**Owner Notification End Date:** MAR 28, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 20, 2018	2017-4	37	26	0	0
3	OCT 12, 2017	2017-3	37	23	0	0
2	JUL 18, 2017	2017-2	37	17	0	0
1	APR 28, 2017	2017-1	37	9	0	0

This Document Last Updated : JAN 25, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.