

**Recall Quarterly Report****17V-186**

**Manufacturer Name :** Trail King Industries, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 17V-186 /  
**Recall Subject :** Fifth Wheel Coupler Plate may Crack  
**Owner Notification Beginning Date :** MAR 20, 2017  
**Owner Notification End Date:**



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
12	JAN 08, 2020	2019-4	55	55	0	0
11	OCT 04, 2019	2019-3	55	54	0	0
10	JUL 22, 2019	2019-2	55	54	0	0
9	APR 12, 2019	2019-1	55	54	0	0
8	JAN 07, 2019	2018-4	55	54	0	0
7	OCT 11, 2018	2018-3	55	54	0	0
6	JUL 16, 2018	2018-2	55	54	0	0
5	APR 13, 2018	2018-1	55	51	0	0
4	JAN 04, 2018	2017-4	55	50	0	0
3	OCT 02, 2017	2017-3	55	49	0	0
2	JUL 19, 2017	2017-2	55	35	0	0
1	MAY 18, 2017	2017-1	55	3	0	0

This Document Last Updated : JAN 08, 2020

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.