

Recall Quarterly Report

17V-315

Manufacturer Name : Daimler Trucks North America LLC

NHTSA Recall No. / MFR Recall No. : 17V-315 /FL-738

Recall Subject : Tandem Axle Output Shaft may Fracture

Owner Notification Beginning Date : JUL 07, 2017

Owner Notification End Date: JUL 07, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JUL 30, 2018	2018-2	698	484	0	0
3	APR 30, 2018	2018-1	698	431	0	0
2	APR 30, 2018	2017-4	698	387	0	0
1	OCT 30, 2017	2017-3	698	258	0	0

This Document Last Updated : AUG 14, 2018

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.