

**Recall Quarterly Report****17V-379**

**Manufacturer Name :** BMW of North America, LLC  
**NHTSA Recall No. / MFR Recall No. :** 17V-379 /  
**Recall Subject :** Incorrect Left Rear Assembly Lamp/FMVSS 108  
**Owner Notification Beginning Date :** AUG 11, 2017  
**Owner Notification End Date:** AUG 11, 2017



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 30, 2018	2018-3	92	76	0	0
4	JUL 29, 2018	2018-2	92	73	0	0
3	APR 23, 2018	2018-1	92	64	0	0
2	JAN 25, 2018	2017-4	92	54	0	0
1	OCT 19, 2017	2017-3	92	31	0	0

This Document Last Updated : NOV 05, 2018

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.