

**Recall Quarterly Report****17V-415****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**NHTSA Recall No. / MFR Recall No. :** 17V-415 /HLC**Recall Subject :** Loose Lock Nut May Cause Tie Rod Separation**Owner Notification Beginning Date :** JUL 26, 2017**Owner Notification End Date:** JUL 26, 2017

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	NOV 13, 2017	2017-3	1,761	1,227	466	0

This Document Last Updated : NOV 15, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.